

Oil Field Environmental Incident Summary

Incident: 20151030092949

Date/Time of Notice: 10/30/2015 09:29

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: GYDA 31-6 1H

Field Name: BRIAR CREEK

Well File #: 23888

Date Incident: 10/29/2015

Time Incident: 16:20

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 104

Sec: 30

Qtr:

Location Description:

Submitted By: Mark Turnley

Received By:

Contact Person: Mark Turnley
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels	8	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No risk to persons

Areal Extent:

Potential Environmental Impacts:

No risk to environment

Action Taken or Planned:

Spill was contained inside lined containment. Vac truck was utilized to recover oil and it was placed back into process system. Safety Stand Down to review incident and insure proper work requirements are followed

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 10/30/2015 **Status:** Reviewed - Assigned to Other Agency**Author:** Souder, Taylor**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.